





VENT PIPE PENETRATION

BRAVA SLATE

DETAIL NO.

BS-9

NOT DRAWN TO SCALE